

Stop Use and Recall
IMMEDIATE ACTION REQUIRED

Maniac Loopie Sling

December 8, 2021

Pelican Rope Part Numbers:

A7PE2-16CY-06L, A7PE2-20C1-07L, A7PE2-24C3-08L

⚠ WARNING: All recipients of this mandatory stop use notice must read, understand, and follow all instructions. Failure to do so may result in serious injury or death.

It has been brought to our attention an error in assembly has occurred with Pelican Ropes Maniac Loopie Slings. Fortunately, while there have been NO reported injuries due to this nonconformity, use of the product could result in serious injury or death. Testing of additional Maniac Loopie Slings exhibited lower tensile strengths than required by Pelican Rope and demonstrated the potential to slip under load in certain configurations.

Products included in this notice must be removed from use.

This notice only affects the models listed under the Pelican Part Numbers provided, with identified manufacturing dates between April 1, 2021 and November 22, 2021. Models outside of this date range, including new units are not affected by this notice.

INSPECTION:

Image #1 shows labeling for a 5/8" Maniac Loopie Sling, Part # A7PE2-20C1-07L, and where to find its Manufacturing Date.

Image #2 shows where labeling can be found and the identified point of assembly error.

REPLACEMENT PROCESS:

Please contact Pelican Rope Works Customer Service Department with the following information: Part Number and Quantity of Returning Assemblies. We will replace assembly at no charge to the customer.

Pelican Rope Works
Customer Service Department
Email: customerservice@usrigging.com
Phone: (714) 545-7444 ext.106

We recognize this Recall will be a burden, but safety is our highest priority. We apologize for any inconvenience this recall causes for you and your customers.

| | |
|----|---|
| #1 | PELICAN ROPE A7PE2-20C1-07L Loopie Sling Tech 4-7 WLL Choker: 2,800 lbs Diameter: 5/8" Lot#: 94258 Mfg Date: 10/2021 WARNING! INSPECT ROPE & READ INSTRUCTIONS PRIOR TO USE |
|----|---|

